

AD-A065 578

GAI CONSULTANTS INC MONROEVILLE PA

NATIONAL DAM SAFETY PROGRAM. TROUT RUN DAM (NDI-PA.-481), OHIO --ETC(U)

OCT 78

DACW31-78-C-0052

F/G 13/2


NL

UNCLASSIFIED

OF
AD-A065 578



END
DATE
FILMED
5-79
DDC



MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

LEVEL II

1

AD A0 65578

OHIO RIVER BASIN
TROUT RUN, WESTMORELAND COUNTY
PENNSYLVANIA

NDI No. Pa. - 481

11 Oct 78

6

TROUT RUN DAM

National Dam Safety Program. Trout Run Dam (NDI-Pa.-481), Ohio River Basin, Trout Run, Westmoreland County, Pennsylvania. Phase I Inspection Report.

12 81P

**PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM**

Distribution Unlimited
Approved for Public Release

Contract No. DACW31-78-C-0052

PREPARED FOR

DEPARTMENT OF THE ARMY
Baltimore District, Corps of Engineers
Baltimore, Maryland 21203

PREPARED BY

GAI CONSULTANTS, INC.
570 BEATTY ROAD
MONROEVILLE, PENNSYLVANIA 15146

OCTOBER 1978

DDC

RECEIVED
MAR 13 1979
D

DDC FILE COPY

411 002

79 03 08 038

PHASE I REPORT
National Dam Inspection Program

Trout Run Dam (Hillside Run Dam)

Pennsylvania

Indiana County

Trout Run

21 September 1978

(cont. p. 1)
↓
Inspection Team - GAI Consultants, Inc.
570 Beatty Road
Monroeville, Pennsylvania 15146

Based on a visual inspection, past performance and available engineering data as well as a brief hydrologic and hydraulic investigation, the facility is considered to be in fair condition.

Hydrologic and hydraulic calculations indicate that the facility is capable of passing and/or storing 47 percent of the runoff associated with a PMF event. Hence, in accordance with screening criteria established by the Department of the Army, Office of the Chief of Engineers, the spillway is deemed to be "seriously inadequate".

The dam has a history of seepage problems, and PennDER files make reference to a number of remedial programs which were conducted to remedy the problems. At the time of inspection seepage and/or saturated conditions were observed, in various areas at the toe of the embankment and in an area approximately 20 feet below the dam crest, just to the right of the spillway sidewall. The cumulative effect of the seepage should be evaluated in terms of its possible bearing on the stability of the structure, particularly at higher pool levels.

Based on the above mentioned considerations, it is recommended that the owner:

a. Enlist the services of a registered professional engineer experienced in the design and construction of dams to more accurately assess the adequacy of the discharge system at the facility. Subsequently, the owner should make any modifications deemed necessary to insure that the facility will function adequately during a PMF event.

b. Enlist the services of a registered professional engineer, experienced in design and construction of earthen embankments, to assess the structural adequacy of the embankment under all possible operating conditions. The seepage and saturated areas should be evaluated to determine what effect, if any, they have on the stability of the structure.


i 79 03 08 038


c. Develop a warning system to notify downstream residents should hazardous conditions develop. This should include provisions for round-the-clock surveillance during periods of unusually heavy rainfall.


d. Repair and/or replace the deteriorated portions of the spillway.

GAI Consultants, Inc.

Approved by:


Bernard M. Mihalcin, P.E.


G. K. WITHERS
Colonel, Corps of Engineers
District Engineer



Under the recently revised spillway evaluation guidelines, this dam is considered unsafe, non-emergency.

Date 21 Nov 78

Date 21 Dec 78


ACCESSION TO	
PTIC	White Section <input checked="" type="checkbox"/>
DOC	Duty Section <input type="checkbox"/>
UNANNOUNCED	<input type="checkbox"/>
JUSTIFICATION	
BY	
DISTRIBUTION/AVAILABILITY CODES	
Dist.	AVAIL. and/or SPECIAL
A	

TABLE OF CONTENTS

<u>SUBJECT</u>	<u>Page</u>
SECTION 1 - GENERAL INFORMATION.	1
1.0 Authority.	1
1.1 Purpose.	1
1.2 Description of Project	1
1.3 Pertinent Data	2
SECTION 2 - ENGINEERING DATA	5
2.1 Design	5
2.2 Construction	6
2.3 Operational Procedures	6
2.4 Other Investigations	6
2.5 Evaluation	6
SECTION 3 - VISUAL INSPECTION.	7
3.1 Observations	7
3.2 Evaluation	8
SECTION 4 - OPERATIONAL PROCEDURES	10
4.1 Normal Operational Procedure	10
4.2 Maintenance of Dam	10
4.3 Maintenance of Operating Facilities.	10
4.4 Warning System	10
4.5 Evaluation	10
SECTION 5 - HYDROLOGIC/HYDRAULIC EVALUATION.	11
5.1 Design Data.	11
5.2 Experience Data.	11
5.3 Visual Observations.	11
5.4 Overtopping Potential.	11
5.5 Spillway Adequacy.	11
SECTION 6 - EVALUATION OF STRUCTURAL INTEGRITY	13
6.1 Visual Observations.	13
6.2 Design and Construction Techniques	13
6.3 Past Performance	14
6.4 Seismic Stability.	14
SECTION 7 - ASSESSMENT AND RECOMMENDATIONS FOR REMEDIAL MEASURES	15
7.1 Dam Assessment	15
7.2 Recommendations.	15

TABLE OF CONTENTS

APPENDIX A - CHECK LIST - ENGINEERING DATA	
APPENDIX B - CHECK LIST - VISUAL INSPECTION	
APPENDIX C - HYDROLOGY AND HYDRAULICS	
APPENDIX D - PHOTOGRAPHS	
APPENDIX E - GEOLOGY	
APPENDIX F - FIGURES	
APPENDIX G - REGIONAL VICINITY MAP	



OVERVIEW PHOTOGRAPH OF TROUT RUN DAM

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM
TROUT RUN DAM
NDI# PA 481, PENNDER# 65-78

SECTION 1
GENERAL INFORMATION

1.0 Authority.

The dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.

1.1 Purpose.

The purpose is to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project.

a. Dam and Appurtenances. Trout Run Dam is an earthen embankment with a concrete corewall. The overall length of the structure is 582 feet and its maximum height is 41 feet. The facility is equipped with a spillway on the left abutment as well as a 30-inch diameter cast iron blow-off pipe and a 12-inch diameter supply pipe encased in concrete beneath the embankment. The lines are gated in a control tower located upstream of the corewall of the embankment, left of dam center (see Photograph 1). *(cont on p i)*

b. Location. Trout Run Dam or Hillside Run Dam, as it is locally known, is located on Trout Run in Indiana County, Pennsylvania approximately 3 miles northeast of the community of Derry. Dam, reservoir and watershed are located on the Derry and Wilpen, U.S.G.S., 7.5 minute Quadrangles.

c. Size Classification. Intermediate (41 feet high - 130 acre-feet of storage at the top of the dam).

d. Hazard Classification. High (see Section 3.c.4)

e. Ownership. Borough of Blairsville, 224 South, Stewart Street, Blairsville, Pennsylvania 15717.

f. Purpose of Dam. Water supply serving the Borough of Blairsville.

g. Historical Data. Data available from PennDER files indicate that construction of the facility was initiated on September 1, 1926, by the John F. Casey Company of Pittsburgh,

Pennsylvania. Work was completed in the fall of 1927 without any major modifications or delays.

Numerous inspection reports were issued by predecessors of PennDER beginning shortly after construction. The initial reports made mention of seepage in various areas at the toe of the embankment, flow through drains which emptied into the spillway outlet channel and through the embankment at a point to the right of the right spillway side wall just above the berm. Seepage was also noted near the right valley wall approximately 150 feet downstream of the dam toe.

In November 1932 trenches were excavated downstream of the core wall into the rock foundation in which openings were encountered. Some concrete was subsequently poured and a grouting program initiated to cut off the seepage. An April 1933 Inspection Report suggests that the remedial work was successful although details are not provided. This same report, however, indicates that "considerable leakage" was observed near the toe of the slope at the extreme right end of the embankment.

Subsequent inspection reports make reference to seepage problems in the same areas as mentioned above, however, the frequency of inspections diminishes after the 1940's and little is known about the history and performance of the facility over the last 30 years.

1.3 Pertinent Data.

a. Drainage Area. 2.3 square miles

b. Discharge at Dam Site.

Outlet Works Conduit - Discharge at normal pool \approx 130 cfs.

Spillway Capacity at Maximum Pool \approx 1900 cfs.

c. Elevation (feet above mean sea level).

Top of Dam - 1260.

Maximum Pool Design Surcharge - Not Known.

Maximum Pool of Record \approx 1259.

Normal Pool (spillway crest) \approx 1256.

Upstream Portal Invert Outlet Conduit \approx 1228.

Downstream Portal Invert Outlet Conduit \approx 1228.

Streambed at Centerline of Dam \approx 1218.

Maximum Tailwater - Not known.

d. Reservoir.

Length of Maximum Pool (1260) \approx 1,000 feet.

Length of Normal Pool (1256) \approx 760 feet.

e. Storage (acre-feet).

Spillway Crest \approx 98.

Top of Dam \approx 130.

Design Surcharge - Not known.

f. Reservoir Surface Area (acres)

Spillway Crest \approx 8.0.

Top of Dam \approx 8.0.

g. Dam.

Type - Earthfill with a concrete core wall.

Length - 582 feet.

Height - 41 feet.

Top Width - 12 feet (field measured).

Side Slopes - 2-1/2H:1V

Upstream - 2H:1V

Downstream - 2H:1V

Zoning - Trout Run Dam is an homogenous earth dam although the contract specifications indicate that the more pervious material should be placed downstream of the cut off wall.

Impervious Core - A concrete corewall extends from the foundation to elevation 1259.

Grout Curtain - 3-1/4 inch diameter well casing was placed on 8.0' centers along the centerline of the corewall. No grouting, however, was performed during the initial construction.

h. Outlet Conduit.

1. Blow-off Line.

Type - 30 inch diameter cast iron pipe encased in concrete and buried in a trench beneath the embankment.

Length - \approx 210 feet.

Closure - Valved within gate house accessible from the crest.

2. Supply Line (Embankment Section)

Type - 12-inch diameter cast iron pipe encased in concrete.

Length - \approx 210 feet.

Closure - Valved within gate house accessible from the crest.

Regulating Facilities - Discharge is controlled via a gate located just beyond a concrete block chlorination house located approximately 150 yards downstream of the embankment.

i. Spillway.

Type - Uncontrolled ogee-crested spillway located at the left abutment.

Crest Length - 61 feet.

Channel Length - \approx 260 feet.

Crest Elevation - 1256.

Upstream Channel - Concrete lined forebay extending approximately 40 feet upstream of the weir.

Downstream Channel - Rectangular concrete chute type spillway discharging into the rock lined Trout Run streambed about 260 feet downstream of the weir.

j. Regulating Outlets. The 30-inch diameter blow-off line is controlled by a gate valve on the operating floor of the gate house. The 12-inch diameter supply line is controlled in a similar manner; however, water can enter the gate house structure from two elevations within the reservoir (see Figure 5).

SECTION 2 ENGINEERING DATA

2.1 Design.

a. Design Data Availability and Sources.

1. Hydrology and Hydraulics. No design data are available.
2. Embankment. No design calculations are available. Embankment and subsurface details are provided on as-built drawings and specifications available from PennDER files.
3. Appurtenant Structures. No design calculations are available. Structural details are shown on drawings supplied from PennDER files.

b. Design Features.

1. Embankment. Contract drawings, specifications, and construction reports indicate that the structure is a rolled earthfill structure containing a concrete core wall which was carried down to rock (see Figure 3). The upstream face is mantled with a 12-inch thick layer of stone paving and is sloped at 2.5H:1V. The downstream face is sloped at 2H:1V and the downstream toe is composed of rockfill but it does not appear that any internal drainage system was incorporated into the structure.

2. Appurtenant Structures.

- a) Spillway. The spillway is an uncontrolled concrete chute type structure with an ogee-shaped crest. A concrete cut-off wall extends beneath the spillway to rock as shown on Figure 4. Two smaller concrete cutoffs were constructed in the approach channel of the spillway. The spillway chute is characterized as a curved rectangular channel which empties into a rock-lined portion of the Trout Run channel approximately 260 feet downstream of the crest.

- b) Outlet Works. The facility is provided with a 30-inch diameter blow-off pipe which discharges into the spillway outlet channel. A 12-inch diameter supply line conveys water to a chlorination building located about 150 yards downstream of the dam. Both of these lines are gated within a concrete gate house located atop the dam crest. Details of the outlet system are shown on Figure 5.

c. Design Data and Procedures.

1. Hydrology and Hydraulics. No design data are available. A report dated August 18, 1926, contained in

PennDER files, indicates that the spillway has a maximum discharge capacity of 1900 cfs.

2. Embankment. No information relative to design data and/or design procedures were available.

3. Appurtenant Structures. No design data are available.

2.2 Construction.

Bi-weekly construction reports were prepared by the Borough Manager and are available in PennDER files.

2.3 Operational Procedures.

No operational records are available.

2.4 Other Investigations.

PennDER files indicate that periodic inspections were conducted through 1971. Inspection Reports are numerous for the period 1926 through 1941.

2.5 Evaluation.

a. Availability of Information. General engineering data in the form of contract drawings, specifications, and construction status reports are available from PennDER files. No specific design calculations are available.

b. Adequacy of Data. Sufficient data are available to make a general assessment of the facility.

SECTION 3
VISUAL INSPECTION

3.1 Observations

a. General. The visual inspection of the structure and related appurtenances suggested that the facility is in fair condition.

b. Embankment. The embankment is in conformance with the lines and grades depicted on the contract drawings supplied by PennDER. No signs of slope distress were observed at the time of inspection; however, three areas of seepage were observed at and beyond the embankment toe as well as on the downstream slope just above the berm near right sidewall of the spillway (see Figure 1, Appendix F). All of the seepage from the above areas were previously reported in inspection reports contained within PennDER files.

The embankment is provided with a rock toe at its base and a small pool of water was observed at the toe near the center of the embankment (see Photograph 9). According to the dam caretaker, this pool is drained by two pipes which discharge into the spillway outlet channel approximately 80 feet downstream of the concrete portion of the spillway. Acidic flow from mines above the left abutment also reportedly discharges through one of these drains and is the apparent source of the precipitate seen in Photograph 8. Discharge from these pipes was estimated to equal 6 GPM at the time of inspection. Seepage was also observed near the right side of the valley approximately 150 feet downstream of the dam. Flow in this area is estimated to be less than 5 GPM.

The seepage conditions on the downstream face adjacent to the spillway, near the berm elevation and about 20 feet below the crest seem to be related to a condition which has presented problems to the dam owners since shortly after reservoir filling. PennDER records make reference to trenches which were excavated on the downstream side of the core wall into the rock foundation. It is thought that additional concrete cutoff walls were constructed and at least one grouting program was carried out to eliminate the problem. In any event, the condition still persists and is of concern.

Perusal of the contract drawings (see Figures 3 and 4) indicates that the shortest seepage path through the embankment is at a position just to the right of the spillway. It seems possible that water is passing along or below the dam-foundation contact in this area and emerging in the area just above the berm. It is of further interest to note that boring records (see Figure 6) indicate that drilling water was lost and a broken sandstone encountered while drilling

Borings 3, 4, and 5. Bedding plane joints would be aligned in such a way which would promote the migration of water in a northwesterly direction across the valley. This problem is reinforced upon realization that the cutoff is probably founded on the broken sandstone on the entire left abutment because of the dip of the rock strata in the area.

c. Appurtenant Structures.

1. Gate House, Supply and Blow-off Lines.

Trout Run Dam is provided with a 30-inch diameter blow-off and 12-inch diameter supply pipes both encased in concrete beneath the embankment.

The pipes are gated within a concrete and block gate house located atop the dam crest approximately 100 feet north of the spillway. According to the Borough Manager, all of the valves are in good operating order although none were operated in our presence. The controls on the outlet system were reportedly completely refurbished in 1972.

2. Spillway. The spillway at Trout Run Dam is a concrete chute type structure with an ogee-shaped crest. Ungated discharge is conveyed through the structure for approximately 260 feet where it enters the rock-lined Trout Run stream channel.

Severe scaling was observed on portions of the spillway apron and it was obvious that the structure had been patched over the years. The lowest (in elevation) two apron blocks have apparently moved or settled, but the overall appearance of the structure is good.

3. Reservoir Area. The slopes adjoining Trout Run Reservoir are steep and densely wooded. No signs of slope distress were observed at the time of inspection.

4. Downstream Channel. The area immediately downstream of Trout Run Dam is characterized as a narrow, moderate to steep-sided valley containing Trout Run (or Hillside Run as it is locally known). Numerous homes are located on the floodplain within 4,000 feet of the dam, in addition to the caretaker's residence which is located less than 50 feet from the embankment toe (see Photograph 3). Other improvements located within this reach include secondary road bridges and a 3-track spur of the PennCentral Railroad. Because of the above-mentioned considerations the hazard classification of the facility is "high".

3.2 Evaluation.

The dam and its appurtenances are reasonably well-maintained and in fair condition. There are noticeable

seepage and saturated areas at and beyond the toe of the embankment possibly indicating that the concrete core is ineffective as a cutoff. Saturated conditions were also observed on the downstream slope of the embankment in a large area with upper limits about 20 feet below the crest just to the right of the spillway outlet channel. Geologic conditions (see Appendix E) and an inadequate cutoff may be the primary reasons for the seepage at this location. In any event, the situation requires further study.

The appurtenant structures are reasonably well-maintained; however, scaling and some differential movements between spillway slabs are apparent which require evaluation and general remedial repair.

SECTION 4 OPERATIONAL PROCEDURES

4.1 Normal Operational Procedure.

Excess inflow is passed over the spillway and discharges into the stream channel below (see Photograph 6). The main valve on the supply line is kept open and discharge is controlled from a point downstream of the dam. The blow-off line is reportedly opened twice a year to clean the reservoir bottom near the supply inlet.

4.2 Maintenance of Dam.

A full-time caretaker resides in a home at the toe of the dam. During the past 45 years, maintenance has been provided by the caretaker and Blairsville Borough maintenance personnel. Grass is mowed and periodic maintenance performed on the spillway and gate controls. There is no formal maintenance program; however, the dam appeared to be well maintained.

4.3 Maintenance of Operating Facilities.

The gate controls for the outlet works require little maintenance. According to the Borough Manager, repairs were made in 1972 on the lower sluice gate valve stems and guides, etc. Stainless steel trash racks were also provided at this time. All valves are operated at least twice a year to insure workability.

4.4 Warning System.

There are no formal warning systems in effect at the site; however, a full-time caretaker resides on site.

4.5 Evaluation.

With the exception of some scaling and differential movement in the spillway slabs, the dam and its appurtenances appeared to be well-maintained. Mr. Bailey (Blairsville Borough Manager) is an experienced construction supervisor and is quite knowledgeable of the operation of the facility. A full-time caretaker also resides on site.

A formal warning system should be developed.

SECTION 5 HYDROLOGIC/HYDRAULIC EVALUATION

5.1 Design Data.

No hydrologic or hydraulic data are available.

5.2 Experience Data.

Discharge throughout the supply line is recorded daily and transmitted to the borough office. According to the Borough Manager and the caretaker, the highest recorded water level occurred in 1972 when the reservoir level rose to within 1 to 1.5 feet of the top of the embankment.

5.3 Visual Observations.

On the date of inspection, no conditions were observed which would suggest that the appurtenant structures of the dam would not function adequately during a flood event.

5.4 Overtopping Potential.

The ratio "PMF Peak Flow/Drainage Area" was determined from an empirical curve supplied by the Corps of Engineers, Baltimore District. The curve used was the Ohio River Basin Curve. Based on this curve and a drainage area of 2.3 square miles, peak PMF $Q/A = 1890$ cfs/sq mi and Peak PMF $Q = 4347$ cfs.

The size category is "intermediate" and the hazard rating "high"; consequently the design flood is the PMF (Recommended Guidelines for Safety Inspection of Dams).

Calculations were performed to evaluate the overtopping potential during a PMF event in which 26 inches of runoff was used to determine the inflow volume (3189 acre-ft).

The spillway has a maximum discharge capacity of approximately 1874 cfs. The outlet pipe has a capacity of 130 cfs bringing the total discharge capacity to 2004 cfs. This number is considerably less than the PMF peak inflow of 4347 cfs. Therefore, excess inflow must be stored before being discharged if the dam is not to overtop. Based on a normal pool elevation of 1256 feet and a top of dam elevation of 1260 feet, the available storage is approximately 32 acre-feet. This is significantly less than the required reservoir storage of 1722 acre-feet; therefore, it can be assumed that the dam would overtop if subjected to a storm of PMF intensity.

5.5 Spillway Adequacy.

The hazard rating for the Trout Run facility is "high". In its present condition, the spillway, 30-inch diameter

outlet pipe and dam are capable of passing and/or storing 47 percent of the PMF. It is anticipated that overtopping would result in failure of the dam and would undoubtedly increase the possibilities for loss of life downstream from that which would exist prior to overtopping; consequently, the spillway is considered seriously inadequate.

SECTION 6 EVALUATION OF STRUCTURAL INTEGRITY

6.1 Visual Observations.

a. Embankment. Based on visual observations, the embankment appeared to be well maintained and in fair condition. Several seepage areas or saturated zones were observed adjacent to the spillway, at the embankment toe and downstream.

Although the dam was provided with a concrete core wall which was carried from the top of rock to within one foot of the dam crest, seepage has been a continual problem at the site since it was noted shortly after construction. PennDER files contain references to trench excavations and additional core wall installation as well as remedial grouting programs. Grout pipes were observed protruding from the embankment at numerous points at the time of inspection.

Most of the seepage, observed as saturated areas at the time of inspection is concentrated around the left half of the embankment. It is interesting to note that the preconstruction borings indicate a broken sandstone as foundation material for the entire left abutment (see Figure 6). The drillers logs indicate that water was lost in Borings 3 and 4 at depths of approximately 10 feet and that the drilling water emerged out of the side of the stream bank of Hillside Run (Trout Run) just below the test holes. Compounding the problem is the fact that the dip of the rock strata in the reservoir area is northwest (see Geology in Appendix E) implying that units which crop out within the reservoir can transmit leakage along bedding plane joints beneath the dam.

In any event, saturated conditions were observed near the right sidewall of the spillway just above the elevation of the berm, about 20 feet below the dam crest. Saturated conditions were also observed just beyond the toe and a pool of water exists at the dam toe. These conditions require further evaluation, particularly with respect to their effect on embankment stability.

b. Appurtenant Structures. Based on a visual observation, the spillway appeared to be in good condition. Some severe concrete scaling was noted. Concrete slabs at the discharge end of the spillway had cracked and some differential movement was apparent.

6.2 Design and Construction Techniques.

Actual design data, design computations, or reports were not available for any aspect of the facility.

6.3 Past Performance.

Representatives of the Borough of Blairsville reported that during the rains associated with Hurricane Agnes, in 1972, the water rose to within 1 to 1.5 feet of the top of the dam. Some damage was reportedly done to the concrete and rock lined channel downstream of the spillway.

6.4 Seismic Stability

The dam is located within Seismic Zone No. 1 and because of the saturated conditions along the toe of the dam as well as the uncertainty of materials used in construction, it is possible that even minor earthquake induced dynamic forces could be significant. However, no investigations, calculations, etc., were performed to confirm this statement.

SECTION 7
ASSESSMENT AND RECOMMENDATIONS FOR REMEDIAL MEASURES

7.1 Dam Assessment.

a. Safety. The visual inspection and available engineering data suggest that the dam is in fair condition. The facility has a history of seepage problems, which were observed on the day of inspection. In addition, a brief hydraulic and hydrologic analysis conducted in accordance with U. S. Army Corps of Engineer guidelines indicates that the facility is capable of passing and/or storing 47 percent of the runoff associated with a PMF event without overtopping. The hazard rating for the facility is high. If Trout Run Dam should fail due to overtopping, the hazard to loss of life would be significantly increased, over that which would exist prior to overtopping. Based on criteria established by the Department of the Army, Office of the Chief of Engineers (OCE), the spillway is considered seriously inadequate.

b. Adequacy of Information. The available data is considered sufficient to make a reasonable Phase I assessment of the facility.

c. Urgency. It is suggested that the recommendations listed below be implemented immediately.

d. Necessity for Additional Investigations. The additional investigations, listed below are considered necessary.

7.2 Recommendations.

It is recommended that the owner:

a. Enlist the services of a registered professional engineer experienced in the design and construction of dams to more accurately assess the adequacy of the discharge system at the facility. Subsequently, the owner should make any modifications deemed necessary to insure that the facility will function adequately during a PMF event.

b. Enlist the services of a registered professional engineer, experienced in design and construction of earthen embankments, to assess the structural adequacy of the embankment under all possible operating conditions. The seepage and saturated areas should be evaluated to determine what effect, if any, they have on the stability of the structure.

c. Develop a warning system to notify downstream residents should hazardous conditions develop. This should include provisions for round-the-clock surveillance during periods of unusually heavy rainfall.

d. Repair and/or replace the deteriorated portions of the spillway.

APPENDIX A

CHECK LIST - ENGINEERING DATA

CHECK LIST
 ENGINEERING DATA
 DESIGN, CONSTRUCTION, OPERATION
 PHASE I

NAME OF DAM Trout Run Dam (Hillside
 Run Reservoir)
 ID # PA-481; Pennder# 65-78

ITEM REMARKS SHEET 1

AS-BUILT DRAWINGS

Available from Pennder.

REGIONAL VICINITY MAP

See USGS 7.5 minute Derry and Wilpen Quadrangles.

CONSTRUCTION HISTORY

Compiled from Pennder files.

TYPICAL SECTIONS OF DAM

See Figures 3, 4, and 5.

OUTLETS - PLAN See Figures 4 and 5.

- DETAILS See Figures 4 and 5.
- DISCHARGE RATINGS None available.

RAINFALL/RESERVOIR RECORDS

None available.

ITEM	REMARKS	ID # PA-481	SHEET 2
DESIGN REPORTS	None available.		
GEOLOGY REPORTS	None available.		
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	None available.		
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	Boring records shown on Figure 6 .		
POST-CONSTRUCTION SURVEYS OF DAM	None.		
BORROW SOURCES	Not known.		

ITEM

REMARKS

ID # PA-481

SHEET 3

MONITORING SYSTEMS

None within the embankment. Flow meter on supply line in downstream chlorination building.

MODIFICATIONS

- 1932 - Placed additional concrete downstream of core wall and initiated a grouting program.
- 1972 - Replaced gates and stems, stem guides etc. as well as trash screens.
- 1977 - Minor spillway repairs (minor spillway repair three times in the last nine years.)

HIGH POOL RECORDS

June 1972 - 2-1/2 to 3' of water over spillway (1 ft from top of dam as per caretakers recollection.)

POST CONSTRUCTION ENGINEERING
STUDIES AND REPORTS

None available.

Mr. Bailey (Borough Manager) estimated that sedimentation has reduced reservoir capacity from 44 x 10⁶ to 36 x 10⁶ gallons. Significant sedimentation occurred during lumbering operations in watershed during 1972-73.

PRIOR ACCIDENTS OR FAILURE OF DAM
DESCRIPTION

REPORTS

Minor damage downstream during Agnes. A small access bridge to the caretakers house was lost and some stones were dislodged from the discharge channel sidewalls.

MAINTENANCE
OPERATION

RECORDS

Daily report issued by full-time caretaker indicating discharge through supply line, chlorination data and weather conditions.

ITEM

REMARKS

ID # PA-481

SHEET 4

SPILLWAY PLAN See Figure 4.

SECTIONS See Figure 4.

DETAILS See Figure 4.

OPERATING EQUIPMENT
PLANS & DETAILS

See Figure 5.

NDI #PA-481

CHECK LIST ID # PennDER #65-78
HYDROLOGIC AND HYDRAULIC
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: 2.3 sq. mi.

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 1256 (98 acre-feet)

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): Not known.

ELEVATION MAXIMUM DESIGN POOL: Not known.

ELEVATION TOP DAM: 1260 (130 acre-feet)

SPILLWAY DATA:

- a. Crest Elevation 1256 ft (MSL) at ogee crest.
- b. Type Ogee crested weir.
- c. Weir Length 61 ft.
- d. Channel Length ≈ 260 ft.
- e. Location Spillover Left abutment.
- f. Number and Type of Gates None.

OUTLET WORKS:

- a. Type 30-inch CIP (blow-off)
- b. Location Passes beneath dam left of center and discharges into
spillway outlet channel.
- c. Entrance Inverts ≈ 1228 ft.
- d. Exit Inverts ≈ 1228 ft.
- e. Emergency Draindown Facilities Controlled mechanically from within
the gate house.

HYDROMETEOROLOGICAL GAGES:

- a. Type None.
- b. Location N/A
- c. Records None available.

MAXIMUM NON-DAMAGING DISCHARGE: 2.5 to 3 ft over spillway crest.

APPENDIX B

CHECK LIST - VISUAL INSPECTION

CHECK LIST
VISUAL INSPECTION
PHASE 1

DAM NAME Hillside Run Dam COUNTY Indiana STATE PA ID # PA-481

TYPE OF DAM Earth HAZARD CATEGORY High Pennder # 65-78

DATE(S) INSPECTION 21 September 1978 WEATHER overcast with TEMPERATURE 65 ±
light rain

POOL ELEVATION AT TIME OF INSPECTION 1254.5 M.S.L. TAILWATER AT TIME OF INSPECTION N/A M.S.L.

INSPECTION PERSONNEL:

B. Mihalcin Merle Clawson (Caretaker)
J. P. Nairn Arthur Bailey (Borough Manager)
S. R. Michalski
D. L. Bonk

B. Mihalcin RECORDER

EMBANKMENT

ID# PA-481

Sheet 1

VISUAL EXAMINATION OF

REMARKS OR RECOMMENDATIONS

SURFACE CRACKS

OBSERVATIONS

None observed.

UNUSUAL MOVEMENT OR
CRACKING AT OR BEYOND
THE TOE

None.

SLOUGHING OR EROSION OF
EMBANKMENT AND ABUTMENT
SLOPES

None - Sandstone (slabby, thinly bedded) in both abutments.

VERTICAL AND HORIZONTAL
ALIGNMENT OF THE CREST

Vertical - Good.
Horizontal - Good.

RIPRAP FAILURES

None - Riprap is slabby sandstone = 12" deep, hand placed.

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

JUNCTION OF EMBANKMENT
AND ABUTMENT, SPILLWAY
AND DAM

Good.

ANY NOTICEABLE SEEPAGE (see Figure 1)

Seepage areas:

- (1) Toe of right abutment below the rock drain (small area & 150 ft downstream.)
- (2) Below the toe along the left half of embankment on the flat between dam and spillway channel (small pool at toe.)
- (3) Adjacent to the spillway wingwall slightly above bench level and below crest level.

STAFF GAGE AND RECORDER

No Staff gage. Flow meter in gage house = 100 yds downstream of the dam.

DRAINS

4-inch and 6-inch diameter drains exit about 50' feet from toe into the downstream channel:

- (1) 4-inch drain flowing at 6 gpm - mine acid reportedly piped into exit drain.
- (2) 6-inch drain flowing < 1 gpm.

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	Cast iron (30-inch ID) blow-off pipe discharges into spillway channel.	
INTAKE STRUCTURE	Intake to 30-inch diameter blow-off pipe is submerged. Upper intake to supply line visible in gate house. Gate house structure in good condition.	
OUTLET STRUCTURE	Blow-off line exits into discharge channel downstream of concrete apron.	
OUTLET CHANNEL	Rock-lined trapezoidal channel below spillway chute. No significant obstructions.	
EMERGENCY GATE	Blow-off pipe valved within gate house. Operated twice a year.	

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	Ogee-shaped concrete weir 61.0 ft in length. Weir is in good condition with joints filled with bitumen.	
APPROACH CHANNEL	Concrete approach - slightly silted.	
DISCHARGE CHANNEL	Concrete chute severely scaled. Displacement (vertical) evident in lower slabs. Few open joints observed. spillway is in need of general resurfacing and repair.	
BRIDGE AND PIERS	Wood bridge located = 150 ft downstream of the spillway which provides access to the caretaker's house.	

GATED SPILLWAY
Not Applicable

ID # PA-481

SHEET 5

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

CONCRETE SILL

APPROACH CHANNEL

DISCHARGE CHANNEL

BRIDGE AND PIERS

GATES AND OPERATION
EQUIPMENT

VISUAL EXAMINATION

MONUMENTATION/SURVEYS

None.

OBSERVATION WELLS

None.

WEIRS

None.

PIEZOMETERS

None.

OTHERS

Several old grout pipes evident in the embankment.

RESERVOIR ID # PA-481 SHEET 7

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

SLOPES

Steep, heavily wooded, no signs of instability.

SEDIMENTATION

Not visible but manager estimates = 8 mg storage capacity lost due to siltation.

DOWNSTREAM CHANNEL

ID # PA-481

SHEET 8

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (CONSTRUCTIONS, DEBRIS, ETC.)	Rock lined channel just downstream of spillway empties in to the natural Trout Run channel ~ 100 feet downstream of the dam. The stream passes beneath at least seven bridges before entering McGee Run approximately one mile downstream of the dam.	
SLOPES		Below the dam for a distance of approximately 3000 feet. The valley slopes are wooded and moderate to steep. Beyond this point Trout Run enters the broad valley to the west of Chestnut Ridge.
APPROXIMATE NO. OF HOMES AND POPULATION		At least one dozen homes in the community of Hillside are located in such a position that they could be effected by failure of Trout Run Dam. Population affected - 50.

APPENDIX C
HYDRAULICS AND HYDROLOGY CALCULATIONS

SUBJECT

DAM SAFETY INSPECTION

BY

DLB

DATE

9-22-78

PROJ. NO.

78-501-481

CHKD. BY

DATE

10-23-78

SHEET NO.

1

OF

9



CONSULTANTS, INC.

Engineers • Geologists • Planners
Environmental SpecialistsDAM STATISTICS

MAXIMUM HEIGHT

- 41 FT.

(FIELD MEASURED)

DRAINAGE AREA

- 2.3 sq. mi.

(PLANIMETERED OFF U.S.G.S.
7.5 MINUTE MAP QUADRANGLES)

STORAGE CAPACITY

@ SPILLWAY CREST (EL 1256)^{1/2} 98 ACRL FT. (FIG 1 ; APPENDIX F)@ TOP OF DAM (EL 1260)^{1/2} 130 ACRL FT. (SHEET 8)SIZE CLASSIFICATION

DAM SIZE

- INTERMEDIATE

(REF 2 ; TABLE 1)

HAZARD RATING

- HIGH

(FIELD OBSERVATION)

REQUIRED SDF

- PMF

(REF 2 ; TABLE 3)

REFERENCES

- 1: "WATER RESOURCES BULLETIN; DAMS, RESERVOIRS, AND LAKES"
PENNA. DEPT. OF FORESTS AND WATERS ; BULLETIN NO. 5,
COMPREHENSIVE WATER RESOURCES PLANNING INVENTORY NO. 1, 1970
- 2: "RECOMMENDED GUIDELINES FOR SAFETY INSPECTION OF DAMS"
DEPT. OF THE ARMY - OFFICE OF CHIEF ENGINEER , APPENDIX D
- 3: STANDARD HANDBOOK FOR CIVIL ENGINEERS
F. S. MERRITT , MCGRAW-HILL 1976

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG

SUBJECT DAM SAFETY INSPECTION
TROUT RUN DAM
 BY DLB DATE 9-22-78 PROJ. NO. 78-501-481
 CHKD. BY _____ DATE 10-23-78 SHEET NO. 2 OF 9

gai
 CONSULTANTS, INC.
 Engineers • Geologists • Planners
 Environmental Specialists


$$\text{PMF (PEAK FLOW)} / \text{AREA} = 1890 \text{ CFS / SQ. MI.}$$

(COF E CURVE,
OHIO RIVER BASIN)


$$\text{PMF} = (1890 \text{ CFS / SQ. MI.}) (2.3 \text{ SQ. MI.}) = 4347 \text{ CFS}$$

$$\text{PEAK PMF } Q = 4347 \text{ CFS}$$

SPILLWAY CAPACITY



ASSUME MINOR CREST
 SETTLEMENTS RESTORED TO
 PROPER GRADE (MAXIMUM MEASURED
 SETTLEMENT EQUALS 0.1 FEET)



ALL ELEVATIONS ARE TAKEN FROM
 DRAWING SHEET NO. 5-B TITLED
 "HILLSIDE RUN WATER SUPPLY,
 DETAIL PLANS OF SPILLWAY", DATED
 APRIL 21, 1927. DIMENSIONS HAVE
 BEEN FIELD VERIFIED

THIS PAGE IS BEST QUALITY PRACTICABLE
 FROM COPY FURNISHED TO DDC

SUBJECT DAM SAFETY INSPECTION
TROUT RUN DAM
BY DIB DATE 9-22-78 PROJ. NO. 78-501-481
CHKD. BY _____ DATE 10-23-78 SHEET NO. 3 OF 9



Engineers • Geologists • Planners
Environmental Specialists

$$Q = CLH^{3/2}$$

(REF 3: EQ 21-121)

L = LENGTH OF SPILLWAY CREST = 61 FT

(SHEET 2)

H = MAXIMUM HEAD OVER SPILLWAY CREST = 4 FT

"

C = COEFFICIENT OF DISCHARGE

(FROM REF 3: FIGURE 21-69)

P/H_d = FOREBAY DEPTH / MAXIMUM HEAD

$$= 2 \text{ FT} / 4 \text{ FT} = 0.5$$

(SHEET 2)

APPROACH SLOPE OF WEIR EQUALS 1H : 1V

"

$$\frac{C_{\text{INCLINED}}}{C_{\text{VERTICAL}}} \approx 1.01$$

(FROM REF 3: FIGURE 21-67)

$$C_{\text{VERTICAL}} \approx 3.8$$

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG

$$C_{\text{INCLINED}} \approx (1.01)(3.8) \approx 3.84$$

$$Q \approx (3.84)(61)(4)^{3/2} \approx 1874 \text{ CFS}$$

PEAK PMF Q (4347 CFS) > MAXIMUM DISCHARGE (1874 CFS)




SUBJECT DAM SAFETY INSPECTION
TROUT RUN DAM
BY DLR DATE 9-25-78 PROJ. NO. 78-501-481
CHKD. BY DATE 10-23-78 SHEET NO. 4 OF 9

Engineers • Geologists • Planners
Environmental Specialists

OUTLET WORKS

(30-INCH DIAMETER BLOW-OFF)



NOTE: THE ABOVE FIGURE IS BASED ON THE DESIGN DRAWING TITLED
"HILLSIDE RUN WATER SUPPLY, SECTION THROUGH DAM AND GATE HOUSE, ETC."
DATED JUNE 22, 1926, SHEET 4-A

USE BERNOULLI'S EQUATION

(REF 3, EQ 21-12)

$$Z_1 + P_1/w + V_1^2/2g = Z_2 + P_2/w + V_2^2/2g + h_f + h_e$$

FOR 30" C.I.P (UNDER MAXIMUM POOL CONDITIONS)

Z_1 = HEIGHT OF INLET ABOVE DATUM	= 0
Z_2 = " " OUTLET " "	= 0
P_1/w = PRESSURE HEAD AT INLET	= 28 FT
P_2/w = PRESSURE HEAD AT OUTLET	= 0
V_1 = VELOCITY AT INLET	= 0
V_2 = " " OUTLET	= SOLVE FOR
g = GRAVITATIONAL CONSTANT	= 32.2 FT/SEC ²

SUBJECT DAM SAFETY INSPECTION
TROUT RUN DAM
 BY DLB DATE 9-25-78 PROJ. NO. 78-501-481
 CHKD. BY _____ DATE 10-23-78 SHEET NO. 5 OF 9



**THIS PAGE IS BEST QUALITY PRACTICABLE
 FROM COPY FURNISHED TO DDQ**

h_f = HEAD LOSS DUE TO FRICTION

$$h_f = f \frac{LV^2}{2gD}$$

(REF 3: EQ 21-30)

L = LENGTH OF PIPE = 153.3'

D = DIAMETER OF PIPE = 2.5'

f = FRICTION FACTOR - BASED ON TURBULENT FLOW WITH AN ASSUMED
 REYNOLD'S NUMBER = 1.0×10^7 AND A COEFFICIENT OF ROUGHNESS
 FOR C.I.P. $\epsilon = 0.00085$ (REF 3: TABLE 21-3)

$$f = 0.017$$

(REF 3: FIG 21-19)

h_e = HEAD LOSS AT INLET

$$h_e = K_e \frac{V^2}{2g}$$

(REF 3: EQ 21-42)

K_e = COEFFICIENT OF FRICTION = 0.50 (REF 3: TABLE 21-7)

SOLVE BERNOULLI'S EQUATION

$$0 + 28' + 0 = 0 + 0 + \frac{V_2^2}{2(32.2)} + \frac{(0.017)(153.3)V_2^2}{(2)(32.2)(2.5)} + \frac{(0.5)V_2^2}{(2)(32.2)}$$

$$28' = (0.016 + 0.016 + 0.008)V_2^2$$

SUBJECT

DAM SAFETY INSPECTIONTROUT RUN DAMBY DLR

DATE

9-25-78

PROJ. NO.

78-501-481

CHKD. BY

DATE

10-23-78

SHEET NO.

6 OF 9Engineers • Geologists • Planners
Environmental Specialists

$$28' / 0.04 = V_z^2$$

$$V_z = 26.5 \text{ FT/SEC}$$

$$Q = VA = (26.5 \text{ FT/SEC})(\pi)(1.25 \text{ FT})^2$$

$$Q = 130 \text{ CFS}$$

$$\text{TOTAL DISCHARGE (SPILLWAY AND BLOW-OFF)} = 1874 \text{ CFS} + 130 \text{ CFS}$$

$$= 2004 \text{ CFS}$$

$$\text{PEAK PMFQ (4347 CFS)} > \text{MAXIMUM TOTAL DISCHARGE (2004 CFS)}$$

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG

SUBJECT DAM SAFETY INSPECTION
TROUT RUN DAM
BY DLB DATE 9-22-78 PROJ. NO. 78-501-481
CHKD. BY DATE 10-23-78 SHEET NO. 7 OF 9

gci
CONSULTANTS, INC.
Engineers • Geologists • Planners
Environmental Specialists

CONSIDER INFLOW RELATIVE TO BOTH OUTFLOW AND STORAGE
USING THE SHORT CUT METHOD AS RECOMMENDED BY NAD

$$P = \frac{\text{MAXIMUM DISCHARGE}}{\text{PEAK PMF } Q} = \frac{2004 \text{ CFS}}{4347 \text{ CFS}} \quad \begin{matrix} (\text{SHEET } 6) \\ (\text{SHEET } 2) \end{matrix}$$

$$P = 0.46$$

$$(1-P) = \frac{\text{REQUIRED RESERVOIR STORAGE}}{\text{INFLOW VOLUME}} = (1-0.46) = 0.54$$

INFLOW VOLUME

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG

$$V = \frac{1}{2} (Q_{\text{IMAX}}) (\text{TIME})$$

$$\text{DURATION TIME} = 34 \text{ HRS}$$

(REF: COF E CURVE,
OHIO RIVER BASIN)

$$V = \frac{1}{2} (4347 \text{ CFS}) (34 \text{ HRS}) (3600 \text{ SEC/HR}) (1 \text{ ACRE} / 43,560 \text{ SQ. FT.}) = 6107 \text{ AC-FT}$$

DETERMINE THE AVERAGE RUNOFF REQUIRED TO PRODUCE THE
ABOVE VOLUME OF INFLOW

$$(6107 \text{ AC-FT}) (1 \text{ SQ. MI.} / 640 \text{ ACRES}) (12 \text{ IN/FT}) / (2.3 \text{ SQ. MI.}) = 49.8 \text{ INCHES}$$

VOLUMES PRODUCED BY RUNOFF IN EXCESS OF 26 INCHES ARE TO
BE RECALCULATED USING 26 INCHES AS AN UPPER BOUND.

$$(26 \text{ INCHES}) (2.3 \text{ SQ. MI.}) (640 \text{ ACRES/SQ. MI.}) (1 \text{ FT} / 12 \text{ IN}) = 3189 \text{ AC-FT}$$

SUBJECT DAM SAFETY INSPECTION
TECUMSEH DAM
BY DLB DATE 9-25-78 PROJ. NO. 78-501-481
CHKD. BY DATE 10-23-78 SHEET NO. 8 OF 9



VOLUME OF INFLOW (RECALCULATED) = 3189 AC-FT

NOTE: Q_{MAX} REMAINS CONSTANT.
DURATION TIME DECREASES IN ACCORDANCE WITH THE DECREASE
IN INFLOW VOLUME.

$$\text{EQUIVALENT DURATION TIME} = \frac{(3189 \text{ AC-FT}) \left(\frac{1}{2} \right) (43,560 \text{ SQ. FT/ACRE})}{(4,347 \text{ CFS}) (3600 \text{ SEC/HR})} = 17.8 \text{ HRS}$$

$(1-P)(\text{INFLOW VOLUME}) = \text{REQUIRED STORAGE}$

$$\text{REQUIRED STORAGE} = (0.54)(3189 \text{ AC-FT}) = 1722 \text{ AC-FT}$$

AVAILABLE STORAGE

RESERVOIR SURFACE AREA (@ NORMAL POOL EL 1256) = 8 ACRES (FIG. 1; APPENDIX F)

AVAILABLE FREEBOARD = 4 FT (SHEET 2)

$$\text{STORAGE AVAILABLE} = 4 \text{ FT} (8 \text{ ACRES}) = 32 \text{ AC-FT}$$

REQUIRED STORAGE (1722 AC-FT) > AVAILABLE STORAGE (32 AC-FT)

ESTABLISH WHAT PERCENT PMF IS PASSED AINL/OR CONTAINED BASED
ON THE ASSUMPTIONS AND CRITERIA FROM PAGES 1 TO 4.

$$(1-P) = \frac{\text{AVAILABLE STORAGE}}{\text{INFLOW VOLUME}} = \frac{32 \text{ AC-FT}}{\left(\frac{1}{2} \right) (Q_{MAX}) (17.8 \text{ HRS}) (3600 \text{ SEC/HR}) (1 \text{ ACRE} / 43,560 \text{ FT}^2)}$$

SUBJECT DAM SAFETY INSPECTION
TROUT RUN DAM
BY DLB DATE 9-25-78 PROJ. NO. 78-501-481
CHKD. BY DATE 10-23-78 SHEET NO. 9 OF 9



Engineers • Geologists • Planners
Environmental Specialists

$$P = \frac{\text{MAXIMUM DISCHARGE}}{\text{PEAK PMF } Q} = \frac{2004 \text{ CFS}}{Q_{\text{IMAX}}}$$

(SHEET 4)

$$\frac{0.74}{Q_{\text{IMAX}}} - \frac{2004}{Q_{\text{IMAX}}} = \frac{32}{0.74 Q_{\text{IMAX}}}$$

$$0.74 Q_{\text{IMAX}} - 1483 = 32$$

$$0.74 Q_{\text{IMAX}} = 1515$$

$$Q_{\text{IMAX}} = 2047 \text{ CFS}$$

$$\text{PEAK PMF } Q = 4347 \text{ CFS}$$

$$Q_{\text{IMAX}} = 47\% \text{ PEAK PMF } Q$$

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG

C

APPENDIX D
PHOTOGRAPHS

PHOTOGRAPH 1 View looking north over the spillway section and along the centerline of the embankment. The valve house is situated within the embankment.

PHOTOGRAPH 2 Detailed view showing the spillway channel and the broad-crested weir in the control section of the spillway.

PHOTOGRAPH 3 View looking down the spillway chute immediately below the spillway weir. The structures in the background are occupied by the dam caretaker and his family.


PHOTOGRAPH 4 View is looking northeast at the reservoir and the watershed area. The pipes in the foreground are remnants of a grouting program conducted circa, 1935.



2



4



1




3

PHOTOGRAPH 5 View of the interior of the gate house.

PHOTOGRAPH 6 View showing the Trout Run channel immediately below the spillway chute. Note the 30-inch diameter blow-off pipe at the end of the chute. The acid mine drainage detailed in Photographs 7 and 8 can be seen in the lower left corner of the picture.

PHOTOGRAPH 7 View showing 4-inch diameter cast iron pipe (left) and a 6-inch diameter terra cotta pipe (TCP) (center) which exit into the discharge channel just downstream of the dam. Flow from the TCP is apparently fed from a small pool at the toe of the dam (behind shrubs in background.)

PHOTOGRAPH 8 Detailed view showing discharge from the 4-inch diameter cast iron pipe shown in the previous view. This discharge reportedly originated at a deep mine located above the embankment on the left abutment.




8



7




6



5

PHOTOGRAPH 9 View showing the small pool at the toe of the dam.

PHOTOGRAPH 10 View looking west (downstream) along the Trout Run channel.
This view is taken from the parking lot of the caretaker's house.



9



10

APPENDIX E

GEOLOGY

GEOLOGY

Trout Run Dam is located in the Allegheny Mountain Section, Physiographic Province of Pennsylvania, on the western flank of the Chestnut Ridge Anticline.

The rock strata below the dam are predominantly sandstones and conglomerates of the Pennsylvania age, Pottsville formation. The rock units which crop out in the valley walls and immediately above the dam are characterized as interbedded shales and sandstones of the Allegheny Formation. Detailed boring logs, depicting subsurface conditions at the site, are shown on Figure 5.

The rock units in the Trout Run Dam vicinity dip to the northwest approximately 850 ft per mile ($\approx 9^\circ$). Locally the dip may more closely approach 15° as evidenced by the cross section shown on Figure 5. In any event, the geologic conditions at the site would be ideal to promote migration of water to the northwest along bedding joints in the broken sandstone unit that crops out on the left abutment.

APPENDIX F

FIGURES

TABLE OF CONTENTS

<u>Figure</u>	<u>Description/Title</u>
1	Sketch - Trout Run Dam
2	Plan of Dam
3	Typical Section and Profile of Dam
4	Detail Plans of Spillway
5	Section Through Dam at Gate House, etc.
6	Test Holes Along Proposed Core Wall No. 1

SUBJECT

SKETCH - TROUT RUN DAM

BY

SKP/JAN

DATE

10-12-78

PROJ. NO.

73-501-481

CHKD. BY

JAN

DATE

11-10-78

SHEET NO.

1 OF 1

gai

CONSULTANTS, INC.

Engineers • Geologists • Planners
Environmental Specialists




FIGURE 1

LEGEND


SEE PAGE

1. SATURATED ZONE

2. SEED


THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

NOTE: SKETCH
NOT TO SCALE



THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO ADC

THIS
FROM



HILLSIDE RUN Water Supply

In Derry Twp, Westmoreland Co.
FOR

BLAIRSVILLE BOROUGH
Indiana County

Map showing revised location of Reservoir, Spillway,
relocation of Township Road and Test Holes.

Scale: 1"=50'



June 22, 1926

T. C. North
Borough Manager

Sheet No. 19


THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC



3


THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG



Note A:

The extent of drilling and grouting will be determined after core wall excavation has been completed to foundation line. The drilling and grouting will be done only in the portions of the foundation which indicate a fractured condition. In the portions of the dam where drilling and grouting is not done the 3 1/2' well casing will be placed in the core wall as shown to permit of subsequent drilling and grouting if the same is required in the future.

Note: No drilling or grouting was done and 3 1/2' Well Casing was placed for full length of Core Wall to foundation line as shown.





Note:

See detail plans of special construction of 20 ft section of Core Wall opposite Gate House Sta 3+22.7 to Sta 3+42.7


Plan of Vertical Core Wall Joint
Core Wall constructed in 30 ft Sections, 12 ft Lifts and keyed as shown.

Scale: 3/4" = 12'



Horizontal Construction Joint
Sections showing method of keying horizontal construction joints in Core Wall.


Scale: 3/4" = 12'




Note: The upper 12' of Core Wall Embankment to be lined with selected rock and covered with fertilizer fertilizer and sown in to grass seed. (The covering with fertilizer and the sowing with grass seed is not included in the Reservoir Contract.)

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC



Profile on E. of Core Wall
Scale: 1"=20'



Section Through Dam

Showing Typical Section

Sta 5+0 Scale: 1"=10'


AS CONSTRUCTED

HILL
W
In Derry
BLAIRSVILLE
Ind.
Typical Section
Scales: As Shown

T.C. North
Dorough

2

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDO



Note: Surface of ground within limits of embankments to be cleared of all brush and trees, Rocks 1' and larger, and all stumps to be grubbed out to depth of atleast 12" below surface. The top layer of leaving sticks and top soil to be scraped off for a depth of 12" or more, as instructed. The surface of all borrow pits must be cleared and scraped in a similar manner and material placed in embankments must be free from roots or other foreign matter. The surfaces of concrete core wall and pipe casing are not to be rubbed. If blasting is required for core wall foundation, very light charges of explosives must be used and work done with extreme care to prevent shattering of the rock in sides and bottom.

HILLSIDE RUN Water Supply

In Derry Twp. Westmoreland Co.

FOR

BLAIRSVILLE BOROUGH
Indiana County

Typical Section & Profile of Dam


Scales: As shown

May 4, 1928
Superseding Sheet No. 3 - Jan. 1, 1928
and Sheet No. 3A - June 22, 1928







T. C. North
Borough Manager

FIGURE 3

Sheet No. 3-B



THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC



THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDQ





FIGURE 4 (1 of 2)

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG



THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

Plan
Scale: 1" = 20'

Section D-D
Scale: 1" = 10'

Section E-E
Scale: 1" = 10'

Ground

Paving sloped 6" to center

12" Farm drain tile laid in stone filled trench 20" wide by 18" deep

Section D-D

Scale: 1" = 10'

Outlet of 30" Flush Line

Old Carb Stone Wall

Rough Stone & Boulders Floor

Depth of 12" Cut-off Wall to be determined

12" Supply Line to Blairsville

Present Ground Surface

Concrete Floor Sub.

130' Flush Line

12" Supply

20' 20' 20' 20' 20' 20' 20' 20' 20' 20'

Ground

Embankment

Section E-E


Scale: 1" = 10'

AS CONSTRUCTED

AS CONSTRUCTED

2

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG



Profile on \pm of Spillway

Scales: Hor. 1"=20'
Ver. 1"=10'

HILLSIDE RUN Water Supply

In Derry Twp., Westmoreland Co.

FOR

BLAIRSVILLE BOROUGH
Indiana County

Detail Plans of Spillway

Scales: As shown

Apr. 21, 1927

T. C. North
Borough Manager


Superseding
Sheet No. 3-A, June 22, 1925
Sheet No. 3, June 4, 1926

AS CONSTRUCTED

FIGURE 4 (2 of 2)

Sheet No. 5-B

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG




Floor Plan of Gate House
Scale: 3/16" = 12"


Note:
See detail plans of special construction
20 ft. section of Core Wall opposite Gate
Sta. 3+05 to Sta. 3+25



Section B-B.
Scale: 3/16" = 12"




Section A-A.
Scale: 3/16" = 12"



FICABLE

White Pine Door
8' 6" x 1 1/2"


Gate House




Sectional Plan of Gate House
Scale: 3/16" = 1'

Plans of special construction of
of Core Wall opposite Gate House
Sta. 3+25 to Sta. 3+25

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC




Section Through Dam
Showing Gate House, Intake & Discharge Lines
Sta. 3+15 Scale: 1" = 10'



Longitudinal Section of Gate House
Scale: 3/16" = 1'

3



HILLSIDE RUN
Water Supply
in Derry Twp., Westmoreland Co.
FOR
AIRSVILLE BOROUGH
Indiana County

•Scales: As shown

June 22, 1926


T. C. North
District Manager

(Superseding Sheet No. 4
Dated - Jan. 1, 1926)


FIGURE 5

Sheet No. 4-A

**THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC**




THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDO



2

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC



Note: See Sheet No. 18 for Elevation of Dam,
Spillway, etc. This Sheet is furnished
for foundation Test Hole information only.

HILLSIDE RUN Water Supply

In Derry Twp. Westmoreland Co.

FOR

BLAIRSVILLE BOROUGH

Indiana County

Test Holes along Proposed Core Wall No. 1

Scales: Hor. 1"=20'
Ver. 1"=10'


June 22, 1926

T. C. North
Borough Manager

FIGURE 6

Sheet

APPENDIX G
REGIONAL VICINITY MAP



WILPEN, PA.

N4015—W7907.5/7.5

1964

PHOTOREVISED 1973
ANS 5164 I SW—SERIES V831

DERRY, PA.

N4015—W7915/7.5

1964

PHOTOREVISED 1973
ANS 5164 IV SE—SERIES V831